


CIRCUIT DRAWN WITH
POWER SUPPLY OFF



NOTE :- CPT REQUIRES
EXTERNALLY SUPPLIED
24VDC SUPPLY

RELAY R1 CAN BE CONFIGURED TO
INDICATE ANY ONE OF THE FOLLOWING:-

- 0 DISABLED
- 1 REMOTE CONTROL AVAILABLE
- 2 FAULT
- 3 FULLY OPEN
- 4 FULLY CLOSED
- 5 FORCE TRIP OPENING
- 6 FORCE TRIP CLOSING
- 7 FORCE TRIP ANY POSITION
- 8 FAILSAFE OPERATION

<p>UPS SOCKET FOR CVL5000 / CVQ6000</p> <p>SK22</p>	<p>CVL1000/1500/5000/ CVQ2400/6000 RESISTOR PACK FITTED TO SK4 IF NO SOLINOID FITTED.</p> <p>SK4 LOAD RESISTOR.</p>	<p>WHEN MANUAL OVERRIDE IS FITTED MOTOR DISABLE SWITCH FITTED IN SERIES WITH THERMOSTAT (SK16)</p>
---	---	--

Iss	Date	Chkd	Revision Details	www.rotork.com	CVA, D/C SUPPLY, N/O CONTACT LOCK SOLENOID + MOR, & HART
2	190312 PMJ	PJW	NOTES ADDED + SK22.		
1	070311 ARD	PJW	First Issue.	ROTORK CONTROLS LTD BATH, BA1 3JQ ENGLAND Tel:01225-733200	ROTORK CONTROLS INC ROCHESTER NY 14624, USA Tel:585-247-2304
Drawn by: A.Dixon Date : 070311 Base WD: C12-00 Job No : -- MI No : --					Circuit Diagram No C12-10 Issue No 2