


CIRCUIT DRAWN WITH  
POWER SUPPLY OFF



RELAY R1 CAN BE CONFIGURED TO INDICATE ANY ONE OF THE FOLLOWING:-

- 0 DISABLED
- 1 REMOTE CONTROL AVAILABLE
- 2 FAULT
- 3 FULLY OPEN
- 4 FULLY CLOSED
- 5 FORCE TRIP OPENING
- 6 FORCE TRIP CLOSING
- 7 FORCE TRIP ANY POSITION
- 8 FAILSAFE OPERATION

|   |   |  |
|---|---|--|
| <p>UPS SOCKET FOR CVL5000 / CVQ6000</p> <p>SK22</p> | <p>CVL1000/1500/5000/ CVQ2400/6000 RESISTOR PACK FITTED TO SK4 IF NO SOLINOID FITTED.</p> <p>SK4 LOAD RESISTOR.</p> | <p>WHEN MANUAL OVERRIDE IS FITTED MOTOR DISABLE SWITCH FITTED IN SERIES WITH THERMOSTAT (SK16)</p> |
|---|---|--|

| Iss | Date   | Chkd | Revision Details |
|-----|--------|------|------------------|
| 1   | 191114 | PJW  | First Issue.     |

[www.rotork.com](http://www.rotork.com)

CVA, D/C SUPPLY, N/C CONTACT.

ROTORK CONTROLS LTD  
BATH, BA1 3JQ  
ENGLAND  
Tel:01225-733200

ROTORK CONTROLS INC  
ROCHESTER  
NY 14624, USA  
Tel:585-247-2304

Drawn by: PJW  
Date : 191114  
Base WD: C11-00  
Job No : --  
MI No : --

|                    |          |
|--------------------|----------|
| Circuit Diagram No | Issue No |
| <b>C11-00</b>      | <b>1</b> |