


CIRCUIT DRAWN WITH
POWER SUPPLY OFF



RELAY R1 CAN BE CONFIGURED TO INDICATE ANY ONE OF THE FOLLOWING:-

- 0 DISABLED
- 1 REMOTE CONTROL AVAILABLE
- 2 FAULT
- 3 FULLY OPEN
- 4 FULLY CLOSED
- 5 FORCE TRIP OPENING
- 6 FORCE TRIP CLOSING
- 7 FORCE TRIP ANY POSITION
- 8 FAILSAFE OPERATION

UPS SOCKET FOR
CVL5000 / CVQ6000



SK22

CVL1000/1500/5000/
CVQ2400/6000
RESISTOR PACK
FITTED TO SK4 IF NO
SOLINOID FITTED.



SK4 LOAD RESISTOR.

WHEN MANUAL
OVERRIDE IS FITTED
MOTOR DISABLE
SWITCH FITTED IN
SERIES WITH
THERMOSTAT (SK16)

Iss	Date	Chkd	Revision Details
3	160312 PMJ	AMW	NOTES ADDED + SK22.
2	280909 BJS	AGM	Voltage source added for CPT.

www.rotork.com

ROTORK CONTROLS LTD
BATH, BA1 3JQ
ENGLAND
Tel:01225-733200

ROTORK CONTROLS INC
ROCHESTER
NY 14624, USA
Tel:585-247-2304

CVA, A/C SUPPLY, N/O CONTACT.	
Drawn by: D.Adams Date : 081008 Base WD: C00-00 Job No : -- MI No : --	Circuit Diagram No C00-00 Issue No 3