

CIRCUIT IS DRAWN FOR A VALVE IN THE FULLY CLOSED POSITION

Circuit Diagram No - Issue No

6P32Q60 - 01

TRANSFORMER TAPPING OPTIONS

TAP	NOM50/60HZ	50HZ	60HZ
X	380/440	342-418	396-484
Y	400/460	360-440	414-506
Z	415/480	373-457	432-528

JUMPER AT LK2 FOR TAPPING X  
 JUMPER AT LK3 FOR TAPPING Y  
 JUMPER AT LK4 FOR TAPPING Z

OT/LS - OPEN TORQUE/LIMIT SWITCH.  
 CT/LS - CLOSE TORQUE/LIMIT SWITCH.  
 OAS - OPEN AUXILIARY SWITCH.  
 CAS - CLOSE AUXILIARY SWITCH.

WIRES ARE IDENTIFIED AT EACH END BY  
 TERMINAL NUMBER OR NUMBER SHOWN.

FS1 - 100 mA


FS2 - 1 A

FS3 - 250 mA

TERMINALS 4 & 5 FUSED  
 INTERNALLY AT 160mA

12W (MAX) HEATER FITTED AS STANDARD.  
 UNLESS OTHERWISE REQUESTED, HEATERS  
 FITTED WILL BE : 240V (5.62K OHM).

E.S.D. CONTROL SIGNAL VOLTAGE MUST  
 BE EQUAL TO OR GREATER THAN ALL  
 OTHER CONTROL SIGNAL VOLTAGES.



Iss	Date	Chkd	Revision Details
01	230218	JS	FIRST ISSUE

**www.rotork.com**  
 ROTORK CONTROLS (INDIA) PRIVATE LTD  
 28B, AMBATTUR INDUSTRIAL ESTATE (NORTH),  
 AMBATTUR, CHENNAI - 600 098 INDIA.  
 Tel:044-39555600

Q-PAK. + POT. + HEATER + C.P.T  
 Drawn by: JS  
 Date : 230218  
 Base WD:  
 Job No : --  
 MI No : .

Circuit Diagram No	Issue No
6P32Q60	1